

(i)

IVSEC Firmware Update - NR308XB/NR316XB

Prerequisites:

- Laptop / PC with internet connection
- Monitor and mouse connected to the NVR
- USB flash drive (formatted with FAT32)
- Download required firmware version (refer to page 2 of this document)
- Click <u>HERE</u> to watch a video demonstrating steps to upgrade the NVR

Once the NVR has been upgraded to the latest firmware version you will be able to perform future NVR updates using online upgrade or via the VMS application.

1. Check the silver sticker on the top of the IVSEC Recorder. Confirm the model number is NR308XB as per image below. Installing the incorrect firmware can cause your NVR to fail.



NOTE: The NR308XB and NR316XB NVRs use the same firmware file

2. Check the software version that is currently installed on the NVR by clicking -

					iV	SEC		
		Information	Channel Information	Record Info	Network Stat	е	×	
INTELLIGENT VIDEO SECUR	Device ID Device Name		000000	000000				
			NR308XB					
	Device Type		NR308XB	DM-370				
	Hardware Version		DM-370			· · · · · · · · · · · · · · · · · · ·		
	Software Version		V8.1.0-202	V8.1.0-20210719		543 S		
	IE Client Version		V1.0.0.120	V1.0.0.120		it. Sint		
	Video Format		PAL					
	HDD Volume			1863G				
	IP Addres			192.168.1.109				
	IPv6 Addr	ess		fe80::5ae8:76				
	Web			80,80				
iVSEC	Client			9000,9000				
	MAC Address			58-E8-76-58-E8-76				
	Network S	State		Connect success				
	P2P ID		MU2FKZZJ	53NJMU2FKZZ	7	7		
						05/00/0004	00 54 40	
Ħ. 田 田 ŀ ŀ ŀ · • ** 🖫					<u>ک</u> 1	(i) 25/08/2021	00:51:19	



- 3. If your software version (as inspected in step 2) is V8.1.0-20200923 and earlier than V8.1.0-20210719
- a. Click <u>HERE to download V8.1.0-20210719</u>
- b. Insert USB flash drive to your computer. Copy filename: N57XE_V191128V200923V200923V210719V210719V210719_W.sw to USB
- c. Insert the USB flash drive into one of the recorder's USB ports.
- d. Click <u>HERE</u> to watch a video demonstrating steps to upgrade the NVR using a USB stick (0-50 seconds of the video)
- e. Wait approx. 5-8 minutes for the firmware upgrade process to complete.
- f. Upon upgrade completion the IVSEC login screen will appear. Login to the NVR and repeat step 2 to ensure the software version has updated to V8.1.0-20210719
- 4. Once the NR308XB has been upgraded to V8.1.0-20210719 you will be able to perform online updates as they become available as shown in video link <u>HERE</u>.

If you require additional support, please email <u>service@ivsecurity.com.au</u> with your NVR model, serial number, a brief description of the issue and your contact details